

Amendments and Clarifications to Current Document

The following document has been published containing minor errors or ambiguities. These are listed below with the amended text.

The changes will be incorporated into the document during the next revision of the document.

Document number	GK/RT0031	Document issue	Four	Document issue date	February 2002
Title:	Lineside signals and Indicators				
Section:	B	Clause number	4.1.2 and 14.1		
Amendment text	<p>It has become necessary to clarify that the lights in flashing double yellow aspects and SPAD indicators flash in synchronism and in the same phase.</p> <p>B4.1.2, Table 1: Amend 'aspect' entry to read: 'Two yellow lights displayed vertically, flashing in synchronism and in the same phase.'</p> <p>B14.1: amend first para. to read: 'A SPAD indicator (Figure 14.1) shall display a steady red light between two red lights, flashing in synchronism and in the same phase, when the signal to which it applies is passed without authority.'</p>				