

Changes from Catalogue and CD-Rom Issue Three, June 2008

Document Number / Title	New	Cancelled	Comments	Date Document comes into force	Document ceases to be in force from
ATOC/AC0P013 – Issue 1 ATOC Approved Code of Practice on Driver Licensing		●			Immediate
ATOC/GPG018 - Issue 1 ATOC Good Practice Guide – Railway Undertaking Input to Railway Strategic Safety Plan 2009 - 2014	●			Immediate	
GE/RT8001 – Issue 16 Changes to the national operations publications for August	●		Supersedes GE/RT8001 Iss 15	Immediate	
GE/RT8001 – Issue 15 Changes to the national operations publications for August		●			Immediate
GC/RT5203 – Issue 3 Infrastructure Requirements for Personal Safety in Respect of Clearances and Access		●	Superseded by GO/RT3413 Iss 1		October 2008
GM/RT2466 – Issue 2 Railway Wheelsets	●		Supersedes GM/RT2466 Iss 1 GM/RC2566 Iss 1	October 2008	
GM/RT2466 – Issue 1 Railway Wheelsets		●	Superseded by GM/RT2466 Iss 2		October 2008
GM/RT3279 – Issue 6 High Visibility Clothing	●		Supersedes GO/RT3279 Iss 5	October 2008	
GM/RT3279 – Issue 5 High Visibility Clothing		●			October 2008
GO/RT3251 – Issue 4 Train Driving		●	Superseded by GO/RT3451 RIS-3751-TOM		October 2008
GO/RT3255 Train Working – Competence and Fitness		●	Superseded by GO/R3451 Iss 1		October 2008
GO/RT3413 – Issue 1 Provision of Information and Signs for Access on the Railway	●		Supersedes GC/RT5203 Iss 3	October 2008	
GO/RT3451 – Issue 1 Train Movement – Staff Suitability and Fitness Requirements	●		Supersedes GO/RT3251 Iss 4 GO/RT3255 Iss 2	October 2008	
RIS-3751-TOM – Issue 1 Train Driver Selection	●		Supersedes GO/RT3251 Iss 4 GO/RT3551 Iss 3	October 2008	
GM/RC2494 – Issue 1 Recommendations for Railway Wheelset Design	●			October 2008	
GM/RC2495 – Issue 1 Recommendations for Railway Wheelset Manufacture and Assembly	●			October 2008	

Document Number / Title	New	Cancelled	Comments	Date Document comes into force	Document ceases to be in force from
GM/RC2496 – Issue 1 Recommendations for Railway Wheelset Maintenance	●			October 2008	
GM/RC2566 – Issue 1 Recommendations for Railway Wheelsets		●	Superseded by GM/RT2466 Iss 2		October 2008
GO/RC3551 – Issue 3 Approves Code of Practice for Train Driving		●	Superseded by GO/RC3561 Iss 1 RIS-3751-TOM Iss 1 RS/221 Iss 1 RS/232 Iss 1 RS/701 Iss 1		October 2008
GO/RC3555 – Issue 1 Railtrack Approved Code of Practice – Train Working		●	Superseded by GO/RC3561 Iss 1 RS/232 Iss 1 RS/701 Iss 1		October 2008
GO/RC3561 – Issue 1 Recommendations for Train Movement – Staff Suitability and Fitness Requirements	●		Supersedes RS/503 Iss 1 RS/505 Iss 1 RS/506 Iss 1 RS/507 Iss 1 GO/RC3551 Iss 3 GO/RC3555 Iss 1	October 2008	
GE/GN8516 - Issue 1 Guidance on Recording and Monitoring of Spoken Safety Communications	●			October 2008	
GE/GN8522 – Issue 1 RIDDOR 1995 – Supplementary Guidance on Statutory Reporting		●			Immediate
GE/GN8579 – Issue 1 Guidance on Digital Wireless Technology for Train Operators	●			October 2008	
GK/GN0554 - Issue 1 Guidance on Radio Electronic Token Block (RETB)	●			October 2008	
GM/GN2498 – Issue 1 Guidance on Wheelset Handling Storage and Transportation	●			Immediate	
RS/221 – Issue 1 Good Practice Guide to Train Driver Training	●		Supersedes GO/RC3551 Iss 3	October 2008	
RS/232 – Issue 1 Good Practice guide on Cognitive and Individual Risk Factors	●		Supersedes GO/RC3551 Iss 3 GO/RC3555 Iss 1	October 2008	
RS/503 – Issue 1 Good Practice Guide on Laser Eye Surgery		●	Superseded by GO/RC3561 Iss 1		October 2008

Document Number / Title	New	Cancelled	Comments	Date Document comes into force	Document ceases to be in force from
RS/505 – Issue 1 Good Practice Guide on Rail Workers and Diabetes – General Guidance		●	Superseded by GO/RC3561 Iss 1		October 2008
RS/506 – Issue 1 Good Practice Guide on Rail Workers and Diabetes – Guidance for Medical Assessors		●	Superseded by GO/RC3561 Iss 1		October 2008
RS/507 – Issue 1 Good Practice Guide on Colour Vision Requirements for Rail Workers		●	Superseded by GO/RC3561 Iss 1		October 2008
RS/701 – Issue 2 Good Practice Guide on competence Review and Assessment	●		Supersedes GO/RC3551 Iss 3 GO/RC3555 Iss 1 RS/701 Iss 1	October 2008	
RS/701 – Issue 1 Good Practice Guide on competence Review and Assessment		●	Superseded by RS/701 Iss 2		October 2008
RS/702 – Issue 1 Good Practice Guide for Driver Assessment	●		Supersedes GO/RC3551 Iss 3	October 2008	
ONGOING CHANGES FROM PREVIOUS ISSUES					
Document Number / Title	New	Cancelled	Comments	Date Document comes into force	Document ceases to be in force from
GM/RT2130 - Issue 1 Vehicle Fire, Safety and Evacuation	●		Supersedes GM/RT2120 Iss 2 GM/RT2177 Iss 1 GM/RT2300 Iss 1 GM/RT2462 Iss 1 AV/ST9002 Iss 1 AV/ST9005 Iss 2	Immediate	
GM/RC2530 – Issue 1 Recommendations for Rail Vehicle Fire Safety	●			Immediate	
GM/RC2531 – Issue 1 Recommendations for Rail Vehicle Emergency Lighting	●			Immediate	
GM/RC2532 – Issue 1 Recommendations for Rail Vehicle Emergency and Safety Equipment	●			Immediate	
GM/RC2533 – Issue 1 Recommendations for Rail Vehicle Emergency and Safety Information	●			Immediate	
GM/RC2534 – Issue 1 Recommendations for Rail Vehicle Emergency Evacuation	●			Immediate	

Document Number / Title	New	Cancelled	Comments	Date Document comes into force	Document ceases to be in force from
GM/RT2120 – Issue 2 Requirements for the Control of Risks Arising from Fires on Railway Vehicles		●	Superseded by GM/RT2130 Iss 1		Immediate
GM/RT2177 – Issue 1 Emergency and Safety Equipment and Signs on Rail Vehicles		●	Superseded by GM/RT2130 Iss 1		Immediate
GM/RT2300 – Issue 1 Warning Signs & Labels Fitted to Electrical Equipment on Rail Mounted Vehicles		●	Superseded by GM/RT2130 Iss 1		Immediate
GM/RT2462 – Issue 1 Internal Combustion Engines in Rail Vehicles		●	Superseded by GM/RT2130 Iss 1		Immediate
AV/ST9002 – Issue 1 Vehicle Interiors Design for Evacuation and Fire Safety		●	Superseded by GM/RT2130 Iss 1		Immediate
AV/ST9005 – Issue 1 Vehicle Interiors – Communication of Safety and Emergency Information		●	Superseded by GM/RT2130 Iss 1		Immediate